

EXPLANATION

Gulfco Marine Maintenance Site Boundary (approximate)

Monitoring Well Location -Zone A

Temporary Piezometer - \otimes Zone A

(1.22)Vinyl Chloride Concentration (mg/L)

-0.2 - Concentration Contour (mg/L) Variable Contour Interval

- Notes: 1. Concentrations are for the most recent sample collected from each location.
- 2. NA = Not analyzed for this compound.
- 3. J = Estimated value.

GULFCO MARINE MAINTENANCE FREEPORT, BRAZORIA COUNTY, TEXAS

Figure 60


VINYL CHLORIDE CONCENTRATIONS IN ZONE A MONITORING WELLS


PROJECT: 1352	BY: ZGK	REVISIONS
DATE: APRIL, 2011	CHECKED: EFP	


PASTOR, BEHLING & WHEELER, LLC

CONSULTING ENGINEERS AND SCIENTISTS

Source of photo: H-GAC, Texas aerial photograph, 2006.







LEGEND

- No acceptable risk (Final SLERA conclusion)
- Pathway is potentially complete
- □ Pathway is incomplete
- Pathway is not viable
- For South Area soils, pathway is mitigated by lack of complete exposure pathways.
 For North Area soils, pathway is potentially complete.

GULFCO MARINE MAINTENANCE FREEPORT, BRAZORIA COUNTY, TEXAS

Figure 63

CONCEPTUAL SITE MODEL -TERRESTRIAL ECOSYSTEM

PROJECT: 1352	BY: ZGK	REVISIONS
DATE: APRIL, 2011	CHECKED: KHT	

PASTOR, BEHLING & WHEELER, LLC

CONSULTING ENGINEERS AND SCIENTISTS

